

# PERFORMANCE OF STEEL TANKS IN CHILE 2010 AND 1985 EARTHQUAKES

*Patricio Pineda  
G. Rodolfo Saragoni  
Elias Arze Loyer (†)*

**UNIVERSITY OF CHILE**

**January 2012**



# DEDICATION

Professor Elias Arze Loyer †




# GENERAL TOPICS

- **Seismic Activity**
- **Main failures in Chile earthquakes with subduction:**
  - **February 27, 2010 : M=8.8**
  - **March 3, 1985 : M=7.8**
- **Comparison with main types of failures observed in major earthquakes worldwide**
- **Conclusions**

# SEISMIC ACTIVITY




# CIRCUMPACIFIC SEISMICITY






# CIRCUMPACIFIC SUBDUCTION




# SUBDUCTION OF NAZCA PLATE UNDER SOUTH AMERICA PLATE



South American  
Plate


# SUBDUCTION PLATE INTERACTION



- **High seismicity**
- **Large subduction interplate earthquakes**
- **Off shore epicenters**



# RUPTURE AREAS OF EARTHQUAKES IN CHILE



# 2011 JAPAN EARTHQUAKE M=9.0



Similar to Chilean Earthquakes  
With Subduction and Large Tsunami

# **MAIN FAILURES IN MAJOR EARTHQUAKES**

## **PREVIOUS STUDIES**



# Table 1. Observed Tanks Failures on Earthquakes (Pineda (2000))

Earthquake	Mag.	Principal Failures						
		RS	BS	WR	CB	RP	AB	HS
Chile 1960	9.5		X		X	X		X
Alaska 1964	9.2		X			X	X	X
Armenia 1972	7.0	X	X		X			
Loma Prieta 1989	6.9	X	X	X				X
Hokkaido 1993	7.6		X					X
Northridge 1994	6.7	X	X		X	X	X	X
Observed Failures	(%)	50	100	17	50	50	33	83


Rupture of Shell Wall : RS  
 Buckling of Shell Wall (Foot of Elephant) : BS  
 Failures in Joints Wall – Roof : WR  
 Failures in Columns and Beams : CB  
 Rupture in Roof Plates : RP  
 Rupture of Anchorage Bolts : AB  
 Horizontal Sliding : HS

# BUCKLING SHELL – BS (100%)





## HORIZONTAL SLIDING - HS (83%)



# **MOST FREQUENT FAILURES**



**Rupture of Pipes**




**Failures in Joints Wall – Roof**

# COMMENTS

- Tanks shown above are self-anchored
- Mainly designed according to API 650-E (1980)
- Must be review design criteria for self-anchored tanks

# 2010 CHILE EARTHQUAKE





- Off the Coast of Maule and Bio Bio
- M=8.8
- $PGA_h=0.93g$
- $PGA_v=0.69g$
- Duration: 2'45"
- With Large Tsunami



# SANTIAGO INTERNATIONAL AIRPORT



- Capacity: 1300m<sup>3</sup>
- Collapse
- Self-Anchored
- Full when earthquake occurred
- We assume design problems
- Undamaged tanks near
- Far away from the epicenter

# SANTIAGO INTERNATIONAL AIRPORT



# SANTIAGO INTERNATIONAL AIRPORT MASONRY DROP FORCE WATER






# PORT AT CONCEPTION AREA TILTED ONE DEGREE



**Near the Epicenter**

## COMMENTS

- Tank performed well due to use mechanical anchor recommended by NCh2369.Of2003 Chilean Standard
  - Steel tanks were located in industrial and oil zones of Chile
  - Seismic recorders were located near the epicenter
- 



# 1985 CHILE EARTHQUAKE



## Terremoto del 3 de marzo de 1985



- Epicenter off city of Algarrobo
- $M=7.8$
- $PGA_h=0.67g$
- $PGA_v=0.81g$
- Duration: 1'35''
- Without Tsunami

## Table 2. Tank Fails in 1985 Chilean Earthquake (Vera (1992)), Con Con RPC

<u>Tank</u>	<u>H(m)</u>	<u>R(m)</u>	<u>V(m<sup>3</sup>)</u>	<u>Product</u>	<u>Roof</u>	<u>Fail</u>
T-326A	12.2	13	1600	Gasoline	Floating	BS
T-326B	12.2	13	1600	Gasoline	Floating	BS
T-418A	12.2	18.3	3200	Nafta	Floating	BS
T-552 <sup>(1)</sup>	12.2	11.2	1200	Solvent	Floating	BS
T-407A	12.2	13.7	1792	Fuel Oil	Conical	BS
T-320A	12.2	11.2	1200	Fuel Oil	Conical	BS
T-4001A	12.2	11.2	1200	Slop	Conical	BS
T-405A	12.2	18.3	3200	Asphalt	Conical	BS
T-420A	11.6	15.9	2285	Kerosene	Conical	(3)
T-301A	9.8	15.2	1760	Kerosene	Conical	(3)
T-422A	12.2	22.4	4800	Kerosene	Conical	(3)
T-402 <sup>(2)</sup>	12.2	22.4	4800	Gasoline	Conical	Without

(1) Tank more damaged only with break in joint bottom shell, with loss of stored liquid

(2) No damage tank


(3) Slight deformation

## COMMENTS

- All tanks were self-anchored, increment in stress on shell for uplift of wall
- Most of self-anchoring tanks failed were designed according to API 650-E (1980)
- Self-anchored tanks presented primarily fails type BS and HS
- Before 1985 in Chile were not available design codes, was created in 1986
- Incorporate anchor in tanks


# COMPARATIVE ANALYSES

## Freeboard



Large Dispersion

## Allowable Stress



Imperfections in Shell



# CONCLUSIONS

- In 1985 the API Standard did not specify anchored tanks, this was corrected in the 2010 Edition of the code
- Use of mechanical anchoring, has been discussed among Chilean designers for years
- In 2010, no major observed failures, due to tanks being mechanically anchored
- In 1985, repeated failures self- anchored tanks

# CONCLUSIONS

- **Make necessary to use mechanical anchoring for reduce the risk of collapse**
- **Mechanical anchoring seems to increase convective stress**
- **During subduction Chilean earthquakes recorded high vertical seismic components or accelerations**
- **NCh2369.Of2003:**
  - **Factors  $R$  and  $\xi$  for vibrations modes**
  - **Include anchorage of Tanks**

# RECOMMENDATIONS

- In Official Chilean Standard NCh2369.Of2003,  $R_c=4$  must be corrected for  $R_c=1$  (Convective Mode)
- Investigate methods for calculating freeboard with reasonable values due to large dispersion
- Must consider imperfections in formula for buckling stress
- Instrumentation is strongly recommended for tanks

**THANKS FOR YOUR ATTENTION**

